


# Instructions

- 1) Click pole sections together,  
2 short and 1 long



- 2) lay shell flat to ground, zipper closed and on underneath side. Three directional tunnels should be visible on top side. These are in sections, three at front (blue) for the longest pole and 2x2 (green) sections as the backbones for the 2 smaller poles. At this point 4 rings should be visible, 1 at each side and 2 at the rear of the shell, a pin attached to each ring,



- 3) Thread the longest pole through the front tunnel (blue) sections and insert pins into ferrules at each end of the pole, creating a dome shape. Now thread 2 shorter poles (capped end first) through the (green) ridge tunnels and under the front pole. Insert the capped ends into the webbing pockets near to the zipper. Again insert the pins at the rear of the dome into the ferrules at the end of the poles.

- 4) The Aerodome should now be erect and free standing. Ties, sand-pockets and pegs are included for extra stability when needed. Air vents can be opened or closed by using flaps from inside the Aerodome.